LOCATION LIST GUARDRAIL AND END TERMINAL

LOCATION	TYPE OF WORK
201 NE 29th St	Guardrail Repair/Replacement, Timber Post Replacement
2402 Forest Park Blvd	Guardrail Repair/Replacement, Timber/Metal Post Replacement
4228 Carol Ave	Guardrail Repair/Replacement, Timber Post Replacement
5198 Cromwell Marine Creek Rd	SGT Replacement, Guardrail Repair/Replacement
5221 Blacmore Ave	Guardrail Repair/Replacement, Timber Post Replacement
5828 Bowman Roberts Rd	Guardrail Repair/Replacement, Timber Post Replacement
8071 W. Cleburne Rd	Guardrail Repair/Replacement, Timber Post Replacement
900 Oak Grove Rd	Guardrail Repair/Replacement, Timber Post Replacement
9525 Harmon Rd	Guardrail Repair/Replacement/DAT Replacement
Belknap/Weatherford St Bridge over Railroad @ N. Pecan St	Guardrail Repair/Replacement, Timber Post Replacement
Blue Mound Rd @ BUS 287	Guardrail Repair/Replacement/DAT Replacement
Burton Hill Rd @ Merrick St	Guardrail Repair/Replacement, Timber Post Replacement
Decatur Ave @ Beaumont St	Guardrail Repair/Replacement, Timber Post Replacement
Handley Ederville Rd @ Randol Mill Rd	Guardrail Repair/Replacement, Timber/Metal Post Replacement
Handley Ederville Rd bridge over Trinity	Guardrail Repair/Replacement, Timber/Metal Post Replacement
Overton Ridge Blvd @ Chisholm TrlPkwy Ramp	Attenuator Replacement
	201 NE 29th St 2402 Forest Park Blvd 4228 Carol Ave 5198 Cromwell Marine Creek Rd 5221 Blacmore Ave 5828 Bowman Roberts Rd 8071 W. Cleburne Rd 900 Oak Grove Rd 9525 Harmon Rd Belknap/Weatherford St Bridge over Railroad @ N. Pecan St Blue Mound Rd @ BUS 287 Burton Hill Rd @ Merrick St Decatur Ave @ Beaumont St Handley Ederville Rd @ Randol Mill Rd Handley Ederville Rd bridge over Trinity

LOCATION LIST GUARDRAIL AND END TERMINAL

SL No.	LOCATION	TYPE OF WORK
17	Pecan Valley @ Lakeside	Guardrail Repair/Replacement, Timber Post Replacement
18	W Long Ave @ NW 35th St	SGT Replacement, Guardrail Repair/Replacement
19	W Risinger Rd @ Crowley Rd	Guardrail Repair/Replacement, Timber Post Replacement
20	,	Guardrail Repair/Replacement, Timber Post Replacement/ W Beam Connector

SGT: Single Guardrail Terminal